cof c

JAN 24 2005 PA

Customer Number 23446 Docket No. 15-DS-00546

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

| Application of: |) |
|----------------------------------|------------------------------------|
| Ingebrigtsen, et al. |) EXPRESS MAIL NO. EV 436263628 US |
| Patent No: 6,821,252 <i>B</i> 2 |) DATE: January 24, 2005) |
| Issued: November 23, 2004 |) |
| Serial No: 10/063,154 |) |
| Filed: March 26, 2002 |) Certificate |
| For: Harmonic Transducer Element |) JAN 3 1 2005 |
| Structures and Properties | of Correction |

REQUEST FOR CERTIFICATE OF CORRECTION UNDER 37 CFR § 1.322(a)

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Attention: Certificate of Correction Branch

Sir:

Pursuant to 37 CFR § 1.322, Applicants hereby request a Certificate of Correction to be issued for the above-identified U.S. Patent, correcting the patent as noted herein and on attached "Certificate of Correction" form PTO 1050 (Rev. 2-93). Duplicate copies of the form PTO 1050 are attached hereto.

At Col. 8, line 59, delete the symbol "y" after "M1" and substitute therefore --y--.

At Col. 8, line 59, delete the symbol $"_y"$ after "M2" and substitute therefore --y--.

At Col. 13, Claim 7, line 8, delete the symbol $"_y"$ after "M1" and substitute therefore --y--.

At Col. 16, Claim 50, line 54, delete "transmitters" and substitute therefore --transmitter--.

At Col. 17, Claim 53, line 11, delete "al-ray" and substitute therefore --array--.

REMARKS

In accordance with Applicants' request, Applicants' attach hereto two copies of the corresponding form PTO 1050 bearing the requested correction.

The above identified errors are printing errors that are not the fault of the Applicants.

In the event that any additional fees are required for the filing of this response, the Commissioner is authorized to charge Deposit Account No. 070845, or to refund any overpayment thereto.

Respectfully submitted,

McANDREWS, HELD & MALLOY, LTD.

Dated: January 24, 2005

Christopher R. Carroll Registration No. 52,700 Attorney for Applicants 34th Floor 500 West Madison Chicago, Illinois 60661 (312) 775-8000 PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,821,252 B2___

DATED : November 23, 2004

INVENTOR(S): Ingebrigtsen et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

At Col. 8, line 59, delete the symbol "y" after "M1" and substitute therefore --y--.

At Col. 8, line 59, delete the symbol "y" after "M2" and substitute therefore --y--.

At Col. 13, Claim 7, line 8, delete the symbol "y" after "M1" and substitute therefore --y--.

At Col. 16, Claim 50, line 54, delete "transmitters" and substitute therefore --transmitter--.

At Col. 17, Claim 53, line 11, delete "al-ray" and substitute therefore --array--.

MAILING ADDRESS OF SENDER:

McAndrews, Held & Malloy, Ltd. 500 West Madison Street, 34th Floor Chicago, Illinois 60661

Patent No: 6,821,252 No. of add'l. copies @ 50¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,821,252 B2_

DATED : November 23, 2004

INVENTOR(S): Ingebrigtsen et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

At Col. 8, line 59, delete the symbol "y" after "M1" and substitute therefore --y--.

At Col. 8, line 59, delete the symbol "y" after "M2" and substitute therefore --y--.

At Col. 13, Claim 7, line 8, delete the symbol "_y" after "M1" and substitute therefore --y--.

At Col. 16, Claim 50, line 54, delete "transmitters" and substitute therefore --transmitter--.

At Col. 17, Claim 53, line 11, delete "al-ray" and substitute therefore --array--.

MAILING ADDRESS OF SENDER:

McAndrews, Held & Malloy, Ltd. 500 West Madison Street, 34th Floor Chicago, Illinois 60661

Patent No: <u>6,821,252</u> No. of add'l. copies @ 50¢ per page

